

# Low Voltage Jointing Resins

## Resin Packs

CABAC supplies two part packs of resin for smaller joints. This is the same compound as used in the GT series of in-line joints. To mix the resin simply remove the divider and mix the resin in the bag. To pour, simply cut off a corner of the bag and pour.

Catalogue No.	Resin Pack Volume (ml)	Weight (gms)
<b>GAM80</b>	80	120
<b>GAM170</b>	143	212
<b>GAM250</b>	286	420
<b>GAM370</b>	370	547
<b>GAM470</b>	464	685
<b>GAM800</b>	730	1076
<b>GAM1200</b>	1200	1766
<b>GAM1800</b>	1500	2208



**Technical Data** - See page D16.

## Bulk Resin

CABAC's Jointing Resin is a two component system comprising low viscosity polyurethane resin and hardener. The resin cures after mixing to a tough flexible electrically inert mass.

The resins are supplied with gloves, stirrer and instructions, either as a simple resin hardener combination, or as a filled resin.

The product is supplied in tins, and the resin and hardener should be mixed at room temperature for at least two minutes using a wide stirrer to avoid air entrapment. The resin has a pot life of approximately 15 minutes to allow the joint to be filled, and gels in approximately 1 hour and is fully cured after 24 hours.

In ambient temperatures below 20°C follow recommendations in Technical Note below.

### 2 Part Resin

Catalogue No.	Resin Volume (L)	Kit Volume (L)	Weight (kg)
<b>PR2L</b>	2	2	2.2
<b>PR3L</b>	3	3	4.06

### Technical Data

Material	Resin: Polyol blend Hardener: Polymeric aromatic di-isocyanate
Mixing & Curing Times	Mix time: 2 minutes Pot life at 20°C: 15 minutes Gel time: 1 hour Cure time at 20°C: 24 hours
Mix Ratio	Resin to hardener: 100:36 by weight
Specific Gravity	1.08
Shore Hardness	24
Dielectric Strength	11 KV/mm



Certification & Test Reports are available on request.

### Technical Note - Cold Temperatures

Resins do not cure rapidly in temperatures below 20°C. Either raise the ambient temperature or warm the joint, cable and connectors, or use the following procedure:

1. Thermally insulate the joint shell using cloth or newspaper and warm if possible. Warming the cable is the easiest.
2. Mix the resin rapidly, and wait a short while until you feel the heat being generated by the resin hardening process, generally a few minutes max.
3. Rapidly pour the resin mixture into the joint. The largest cause of joint failure is badly mixed resin or decomposition or frothing caused by moisture.

Note: Moisture can originate from a gas flame.